

Driveway/Apron Maintenance

2003

These garage aprons were resurfaced to get a positive drain away from the garage to prevent moisture from going in. Believe these were done in 2003 as a part of the assessment project.

1300-1302	1307-1309	
1310* - just filled in a place at bottom of driveway where asphalt was broken out		
1323-1325-1327	1340-1342	1344-1356

2004

The large driveway for unit 1304 was regraded to get a positive drainage of water correcting a problem with the water going into the garage.

At the same time a positive drainage was done to the adjoining units 1306 and 1308. These driveways were completed with new blacktop.

2010

The following driveways were replaced in October 2010:

1300-1302	1301-1303	1312
1311-1313	1348-1352	1354-1356

Areas in 1306 and 1342 driveways were repaired.

2011 Plan

The following driveways are planned to be replaced in 2011:

1305-1309	1310	1314-1320
1315	1323-1327	1340-1342
1344-1346		

The following driveways are planned to be sealcoated in 2011:

1304-1306	1308
------------------	-------------

Updated Nov. 2010