

WALL REPLACEMENT RECORD

1996	Units 1342-1344 (large wall)
1997	Unit 1346 (north retaining wall) - done with patio
2001	Unit 1305
2002	Unit 1354 and very small wall by 1350
2003	Unit 1308 (tiling installed to carry water away from foundation on south side of unit to the street.
2006	Unit 1323 (done with larger project redirecting water)
2008	Unit 1320 - very large wall
2010	Units 1316-1318 - large wall

Darlene Olson
11/2010